

BULLETIN NO. 36A

## How to Cut Screw Threads in the Lathe



Cutting a Screw Thread.

Price 10 Cents  
Postpaid to Any Address  
Coin or Stamps of Any Country Accepted

**SOUTH BEND LATHE WORKS**  
456 NILES AVE. SOUTH BEND, INDIANA, U. S. A.

©1938

## Screw Threads

The history of the origin and development of the screw thread is lost in antiquity. However, it is known that screw threads were used more than 2000 years ago and that screws and bolts were used for fastening together various parts of the armor worn by ancient Roman warriors. Threaded devices were also used to open and close heavy doors and drawbridges of ancient castles.

The development of modern mechanical devices has been made possible by the invention and development of the screw thread. The most important use of threads is for fastening parts of machinery and equipment together. With screws and bolts parts can easily be assembled and taken apart without damage, but when fastened by other methods, such as welding, rivets, nails, etc., this is not possible.

Screws are also used for transmitting motion, such as the lead screw, cross feed screw, etc. of a lathe, also for leverage as in jack screws, vises and clamps. The screw is also used in precision measuring instruments, such as micrometer calipers, cross feed of lathe, etc.

**South Bend Lathe Works**




Fig. 1. Cutting a Screw Thread in the Lathe.

## How to Cut Screw Threads In the Lathe

Cutting screw threads in the lathe is accomplished by connecting the headstock spindle of the lathe with the lead screw, by a series of gears so that a positive carriage feed is obtained and the lead screw is driven at the required speed with relation to the headstock spindle.

The gearing between the headstock spindle and lead screw may be arranged so that any desired pitch of the thread may be cut. For example, if the lead screw has eight threads per inch and the gears are arranged so that the headstock spindle revolves four times while the lead screw revolves once, the thread cut will be four times as fine as the thread on the lead screw or 32 threads per inch.

The cutting tool is ground to the shape required for the form of the thread to be cut, that is "V," Acme, square, etc. The depth of the thread is determined by adjusting the cross slide.

Either right hand or left hand threads may be cut by reversing the direction of rotation of the lead screw. This may be accomplished either by adding or removing one idler gear in the change gear train, or by shifting the tumbler gears on the headstock.






Fig. 2. American National Screw Thread Form (Formerly U. S. Standard Screw Thread).

#### FORMULA

$$P = \text{Pitch} = \frac{1}{\text{No. Th'ds. Per In.}}$$

$$D = \text{Depth} = P \times .64952$$

$$F = \text{Flat} = \frac{P}{8}$$

## American National Screw Threads

The National Screw Thread Commission in 1928 was authorized by Congress to establish a standard system of screw threads for use in the United States. As a result this commission established the American National Screw Thread System which has been approved by the Secretary of War, Secretary of the Navy, and Congress, and is now generally used by all shops in the United States.

The form of the thread adopted is shown above and tables for both the Fine Thread Series and Coarse Thread Series are given on the opposite page. The tabulation at the bottom of page 3 lists a number of special pitches of screw threads that are commonly used. However, the standard screw threads should always be used, if possible.

A report of the National Screw Thread Commission applying to screw threads, bolts, machine screws, etc. defines the following terms.

### Terms Relating to Screw Threads

**Screw Thread.** A ridge of uniform section in the form of a helix on the surface of a cylinder or cone.

**External and Internal Threads.** An external thread is a thread on the outside of a member. Example: A threaded plug. An internal thread is a thread on the inside of a member. Example: A threaded hole.

**Major Diameter.** (formerly known as "outside diameter"). The largest diameter of the thread of the screw or nut. The term "major diameter" replaces the term "outside diameter" as applied to the thread of a screw and also the term "full diameter" as applied to the thread of a nut.

**Minor Diameter.** (formerly known as "core diameter"). The smallest diameter of the thread of the screw or nut. The term "minor diameter" replaces the term "core diameter" as applied to the thread of a screw and also the term "inside diameter" as applied to the thread of a nut.

**Pitch Diameter.** On a straight screw thread, the diameter of an imaginary cylinder, the surface of which would pass through the threads at such points as to make equal the width of the threads and the width of the spaces cut by the surface of the cylinder.

**Pitch.** The distance from a point on a screw thread to a corresponding point on the next thread measured parallel to the axis.

**Lead.** The distance a screw thread advances axially in one turn. On a single-thread screw, the lead and pitch are identical; on a double-thread screw the lead is twice the pitch; on a triple-thread screw, the lead is three times the pitch, etc.

## American National Standard Screw Threads and Recommended Tap Drill Sizes

**Coarse Thread Series (N.C.)**  
Formerly U. S. Standard

No. or Diam.	Threads Per Inch	Major (Outside) Diameter of Screw	Tap Drill Sizes	Decimal Equivalent of Drill
1	64	.073	53	0.0595
2	56	.086	50	0.0700
3	48	.099	47	0.0785
4	40	.112	43	0.0890
5	40	.125	38	0.1015
6	32	.138	36	0.1065
8	32	.164	29	0.1360
10	24	.190	25	0.1495
12	24	.216	16	0.1770
$\frac{3}{4}$	20	.250	7	0.2010
$\frac{5}{8}$	18	.3125	F	0.2570
$\frac{3}{8}$	16	.375	$\frac{3}{16}$	0.3125
$\frac{3}{16}$	14	.4375	U	0.3680
$\frac{1}{2}$	13	.500	$\frac{25}{64}$	0.4219
$\frac{9}{16}$	12	.5625	$\frac{21}{64}$	0.4843
$\frac{5}{16}$	11	.625	$\frac{17}{64}$	0.5312
$\frac{3}{8}$	10	.750	$\frac{23}{64}$	0.6562
$\frac{1}{4}$	9	.875	$\frac{9}{16}$	0.7656
1	8	1.000	$\frac{3}{4}$	0.875
$1\frac{1}{8}$	7	1.125	$\frac{49}{64}$	0.9843
$1\frac{1}{4}$	7	1.250	$\frac{13}{16}$	1.1093

**Fine Thread Series (N.F.)**  
Formerly S. A. E. Thread

No. or Diam.	Threads Per Inch	Major (Outside) Diameter of Screw	Tap Drill Sizes	Decimal Equivalent of Drill
0	80	.060	$\frac{3}{64}$	0.0469
1	72	.073	53	0.0595
2	64	.086	50	0.0700
3	56	.099	45	0.0820
4	48	.112	42	0.0935
5	44	.125	37	0.1040
6	40	.138	33	0.1130
8	36	.164	29	0.1360
10	32	.190	21	0.1590
12	28	.216	14	0.1820
$\frac{3}{4}$	28	.250	3	0.2130
$\frac{5}{8}$	24	.3125	I	0.2720
$\frac{3}{8}$	24	.375	Q	0.3320
$\frac{3}{16}$	20	.4375	$\frac{25}{64}$	0.3906
$\frac{1}{2}$	20	.500	$\frac{21}{64}$	0.4531
$\frac{9}{16}$	18	.5625	0.5062	0.5062
$\frac{5}{16}$	18	.625	0.5687	0.5687
$\frac{3}{8}$	16	.750	$\frac{17}{64}$	0.6875
$\frac{1}{4}$	14	.875	0.8020	0.8020
1	14	1.000	0.9274	0.9274
$1\frac{1}{8}$	12	1.125	$\frac{13}{16}$	1.0468
$1\frac{1}{4}$	12	1.250	$\frac{11}{16}$	1.1718

## American National Special Screw Threads (N. S.) and Recommended Tap Drill Sizes

No. or Diam.	Threads Per Inch	Major (Outside) Diameter of Screw	Tap Drill Sizes	Decimal Equivalent of Drill
$\frac{3}{4}$	24	.250	4	0.2090
	27		3	0.2130
	32		$\frac{3}{16}$	0.2187
$\frac{5}{8}$	20	.3125	$\frac{13}{64}$	0.2656
	27		J	0.2770
	32		$\frac{5}{16}$	0.2812
$\frac{3}{8}$	20	.375	$\frac{21}{64}$	0.3281
	27		R	0.3390
$\frac{1}{2}$	24	.4375	X	0.3970
	27		Y	0.4040

No. or Diam.	Threads Per Inch	Major (Outside) Diameter of Screw	Tap Drill Sizes	Decimal Equivalent of Drill
$\frac{1}{2}$	12	.500	$\frac{21}{64}$	0.4219
	24		$\frac{21}{64}$	0.4531
	27		$\frac{17}{64}$	0.4687
$\frac{3}{8}$	27	.5625	$\frac{17}{64}$	0.5312
$\frac{5}{16}$	12	.625	$\frac{21}{64}$	0.5469
	27		$\frac{19}{64}$	0.5937
$\frac{3}{4}$	12	.750	$\frac{49}{64}$	0.6719
	27		$\frac{23}{64}$	0.7187
$\frac{1}{4}$	12	.875	$\frac{21}{64}$	0.7969
	18		$\frac{23}{64}$	0.8281
	27		$\frac{21}{64}$	0.8437
1	12	1.000	$\frac{21}{64}$	0.9219
	27		$\frac{21}{64}$	0.9687




Fig. 3. Change Gear Equipment Used on Standard Change Gear Lathes.

## Setting Up Standard Change Gear Lathes\* for Cutting Screw Threads

Screw threads are cut on Standard Change Gear Lathes by engaging the apron half nuts with the lead screw. The pitch of thread to be cut is determined by the number of teeth in the change gears used on the reverse stud and the lead screw, also the compound gears when used.

To set up the lathe for cutting a screw thread, first determine the number of threads per inch to be cut. By referring to the change gear chart attached to the lathe (Fig. 4) the change gears required can be determined. The thread to be cut should be located in the first column under the heading "Threads Per Inch." In the second column under the heading "Stud Gear" is listed the number of teeth in the change gear which should be placed on the reverse stud of the lathe. (See Fig. 3.) In the third column under the heading "Idler Gear" is listed the figure number of the diagram on the index chart showing the correct arrangement of idler gear and compound gears. In the fourth column under the heading "Screw Gear" is listed the number of teeth in the gear to be placed on the lead screw.

After selecting the change gears necessary for cutting the desired thread, place them on the reverse stud and lead screw respectively and connect them with the idler gear and compound gears, as shown on the change gear chart.

\* Procedure for 9-inch "Workshop" Lathe is same as for Standard Change Gear Lathe.

CHART FOR THREADS AND FEEDS				
9-inch SOUTH BEND LATHE				
THREADS PER INCH	STUD GEAR	idler GEAR	SCREW GEAR	AUTO. FEEDS
4	24	FIG. 1	48	
4½	24	FIG. 1	54	
5	16	FIG. 1	40	
5½	16	FIG. 1	44	
6	16	FIG. 1	48	
6½	16	FIG. 1	52	
7	32	FIG. 2	28	
8	32	FIG. 2	32	
9	32	FIG. 2	36	
10	32	FIG. 2	40	
11	32	FIG. 2	44	
11½	32	FIG. 2	46	
12	32	FIG. 2	48	
13	32	FIG. 2	52	
14	32	FIG. 2	56	
16	24	FIG. 2	48	
18	24	FIG. 2	54	
20	16	FIG. 2	40	
22	16	FIG. 2	44	.0156
24	16	FIG. 2	48	.0144
26	16	FIG. 2	52	.0132
27	16	FIG. 2	54	.0128
28	16	FIG. 2	56	.0123
30	16	FIG. 2	60	.0115
32	32	FIG. 3	32	.0108
36	32	FIG. 3	36	.0096
40	32	FIG. 3	40	.0086
44	32	FIG. 3	44	.0078
46	32	FIG. 3	46	.0075
48	32	FIG. 3	48	.0072
52	32	FIG. 3	52	.0066
54	32	FIG. 3	54	.0064
56	32	FIG. 3	56	.0062
60	32	FIG. 3	60	.0057
64	16	FIG. 3	32	.0054
72	16	FIG. 3	36	.0047
80	16	FIG. 3	40	.0043
88	16	FIG. 3	44	.0039
92	16	FIG. 3	46	.0037
96	16	FIG. 3	48	.0036
104	16	FIG. 3	52	.0033
112	16	FIG. 3	56	.0030
120	16	FIG. 3	60	.0028
160	16	FIG. 3	80	.0021

AUTOMATIC FEEDS THROUGH FRICTION CLUTCH

AUTOMATIC CROSS FEED = .375 X LONGITUDINAL FEED



FIG. 1




FIG. 2




FIG. 3

Fig. 4. Change Gear Chart for 9" Standard Change Gear Lathes. Similar Charts are used on other sizes of Standard Change Gear Lathes.

The spacing collar on the lead screw must be placed outside the screw gear, as shown in Fig. 5, when simple gearing is used, and inside the screw gear, as shown in Fig. 6, when compound gearing is used.




Fig. 5. Position of Spacing Collar for Simple Gearing.




Fig. 6. Position of Spacing Collar for Compound Gearing.

## Adjusting Levers of Quick Change Gear Box for Cutting Various Pitches of Screw Threads

The only difference between the Quick Change Gear Lathe and the Standard Change Gear Lathe is that the Quick Change Gear Lathe is fitted with a gear box which permits obtaining various pitches of screw threads without the use of loose change gears. (See Fig. 7.)

The screw thread chart is attached to the gear box, as shown in Fig. 8 below. This chart reads directly in threads per inch. It is only necessary to arrange the levers of the gear box as indicated on the index plate in order to obtain various screw threads and feeds.

The pitch of the thread to be cut is determined by shifting the sliding gear A, top lever B and tumbler lever C of the quick change gear box so that they conform with the thread cutting chart. For example, to cut 3 threads per inch the sliding gear A is pushed in, the top lever B on the gear box is pushed to the extreme left position and the tumbler lever C is placed just below the column in which the thread appears on the index chart. (See Figs. 7 and 8.)




Fig. 7. Quick Change Mechanism used on all South Bend Quick Change Gear Lathes.




Fig. 8. Close-up of quick change gear box.



## Lathe Tools Used for Cutting Screw Threads

The point of the cutter bit must be ground to an angle of  $60^\circ$  for cutting screw threads in the lathe, as shown in Fig. 9 at right. A center gage or angle gage is used for grinding the tool to the exact angle required. The top of the tool is usually ground flat, with no side rake or back rake. However, for cutting threads in steel, side rake is sometimes used.

A formed threading tool is usually used if considerable threading is to be done. Figs. 11 and 12 illustrate two good types of formed threading tools. The formed threading tools require grinding on top edge only to sharpen and therefore always remain true to form and correct angle.

For cutting American National Standard Screw Threads finer than 10 per inch, the point of the tool is usually left sharp or with a very small flat to provide clearance at the bottom of the thread. However, for cutting coarser pitches of threads and when maximum strength is desired, the point of the tool may be ground flat, as shown in Fig. 13. The flat on the point of the tool should be one-eighth of the pitch. (See Fig. 2, Page 2.)

The illustration at the bottom of the page, Fig. 14, shows a gage which may be used for grinding threading tools to the exact angle required for standard screw threads. Note that the gage shows the flat for the point of the tool as well as the exact angle and depth of thread.




Fig. 9. Center gage used for checking angle of cutter bit ground for cutting screw threads.




Fig. 10. Side View of lathe tool cutter bit ground for cutting screw threads.



Fig. 10-A. End View of lathe tool cutter bit ground for cutting screw threads.



Fig. 11. Formed threading tool, solid type.



Fig. 12. Formed threading tool, spring type.



Fig. 14. Standard screw thread tool gage for grinding threading tools.




Fig. 13. Forged steel threading tool.

*When cutting screw threads in steel use plenty of oil and a smooth thread will result.*

# Correct Position of Lathe Tool for Cutting Screw Threads

## For External Threads

The top of the threading tool should be placed exactly on center, as shown in Fig. 15 at right, for cutting external screw threads. Note that the top of the tool is ground flat and is in exact alignment with the lathe center. This is necessary to obtain the correct angle of the thread.

The threading tool must be set square with the work, as shown in Fig. 16. The center gage is used to adjust the point of the threading tool and if the tool is carefully set a perfect thread will result. Of course, if the threading tool is not set perfectly square with the work, the angle of the thread will be incorrect.



Fig. 15. Top of cutter bit should be set on center for cutting screw threads.




Fig. 16. Cutter bit should be set square with work, as shown above, for cutting external screw threads.

## For Internal Threads

The point of the threading tool is also placed exactly on center as shown in Fig. 17 at right for cutting internal screw threads. The point of the tool must be set perfectly square with the work. This may be accomplished by fitting the point of the tool into the center gage, as shown in Fig. 18 at right.

When adjusting the threading tool for cutting internal threads, allow sufficient clearance between the tool and the inside diameter of the hole to permit backing out the tool when the end of the cut has been reached. However the boring bar should be as large in diameter and as short as possible to prevent springing.




Fig. 17. For cutting internal screw threads, top of cutter bit should be set exactly on center.




Fig. 18. Cutter bit should be set square with work, as shown above for cutting internal screw threads.




Fig. 19. Compound rest of lathe set at  $29^\circ$  angle for cutting screw threads.

## Position of Compound Rest for Cutting Screw Threads

In manufacturing plants where maximum production is desired it is customary to place the compound rest of the lathe at an angle of  $29^\circ$  for cutting screw threads. The compound rest is swung around to the right, as shown in Figs. 19 and 20. When the compound rest is set in this position and the compound rest screw is used for adjusting the depth of cut, most of the metal is removed by the left side of the threading tool. (See Fig. 21.) This permits the chip to curl out of the way better than if tool is fed straight in, and prevents tearing the thread. Since the angle on the side of the threading tool is  $30^\circ$ , the right side of the tool will shave the thread smooth and produce a nice finish, although it does not remove enough metal to interfere with the main chip which is taken by the left side of the tool.



Fig. 20. Correct angle of compound rest for thread cutting.




Fig. 21. Action of thread cutting tool when compound rest is set at  $29^\circ$  angle.




Fig. 22. Cutting a screw thread on a precision thread gage.




Fig. 23. Lathe dog should be tight when work is mounted between the lathe centers for cutting screw threads.

## Mounting the Work in the Lathe

When mounting work between the lathe centers for cutting screw threads, make sure the lathe dog is securely attached before starting to cut the thread. If the dog should slip the thread will be ruined. Never remove the lathe dog from the work until the thread has been completed, and if it is necessary to remove the work from the lathe before the thread is finished make sure that the lathe dog is replaced in the same slot in the face plate.

When threading work in the lathe chuck make sure the chuck jaws are tight and the work is well supported. The chuck must be tight enough on the spindle to prevent unscrewing when the lathe is reversed. Never remove the work from the chuck until the thread is finished.

When threading long slender shafts, use a follower rest, as shown in Fig. 26. The center rest may be used for supporting long work such as pipe which is to be threaded on the inside. (See Fig. 27.)




Fig. 24. Chuck jaws should be tight when cutting screw threads.




Fig. 25. Work should be pushed back in chuck and well supported.



Fig. 26. Cutting a long slender screw thread, with the aid of a follower rest.




Fig. 27. Threading the end of a pipe on the inside with a center rest.






Fig. 28. Thread cutting stop attached to dovetail of saddle.

## Adjusting the Thread Cutting Stop

On account of the lost motion caused by the play necessary for smooth operation of the change gears, leadscrew, half nuts, etc., the thread cutting tool must be withdrawn quickly at the end of each cut, before the lathe spindle is reversed to return the tool to the starting point. If this is not done, the point of the tool will dig into the thread and may be broken off. The thread cutting stop may be used for regulating the depth of each successive chip.

The point of the tool should first be set so that it just touches the work, then lock the thread cutting stop and turn the thread cutting stop screw until the shoulder is tight against the stop. When ready to take the first chip run the tool rest back by turning the cross feed screw to the left several times and move the tool to the point where the thread is to start. Then turn the cross feed screw to the right until the thread cutting stop screw strikes the thread cutting stop.

The tool rest is now in the original position, and by turning the compound rest feed screw in  $.002''$  or  $.003''$  the tool will be in a position to take the first cut.

### Micrometer Collar May Be Used in Place of Stop

The micrometer collar on the cross feed screw of the lathe may be used in place of the thread cutting stop, if desired. To do this, first bring the point of threading tool up so that it just touches the work, then adjust the micrometer collar on the cross feed screw to zero.




Fig. 29. Micrometer collar on cross feed screw of lathe.

All adjusting for obtaining the desired depth of cut should be done with the compound rest screw. Withdraw the tool at the end of each cut by turning the cross feed screw to the left one complete turn, return the tool to the starting point and turn the cross feed screw to the right one turn, stopping at zero. The compound rest feed screw may then be adjusted for any desired depth of chip.

## Taking the First Cut on a Screw Thread

### Take Light Trial Cut to Check Lathe Set-up

After setting up the lathe, as explained on the preceding pages, arrange the lathe for a slow, back-geared spindle speed and take a very light trial cut just deep enough to scribe a line on the surface of the work, as shown in Fig. 30. The purpose of this trial cut is to make sure that the lathe is arranged for cutting the desired pitch of thread.

To check the number of threads per inch, place a scale against the work, as shown in Fig. 31 so that the end of the scale rests on the point of the thread or on one of the scribed lines. Count the spaces between the end of the scale and the first inch mark, and this will give you the number of threads per inch.

It is quite difficult to accurately count fine pitches of screw threads, as described above. A screw thread gage as illustrated in Fig. 32 is very convenient for checking the finer pitches of screw threads. This gage consists of a number of sheet metal plates in which are cut the exact form of the various pitches of threads and each plate is stamped with a number indicating the number of threads per inch for which it is to be used.

The final check for both the diameter and pitch of the thread may be made with the nut that is to be used or with a ring thread gage, if one is available. Fig. 33 shows how the nut may be used for checking the thread. The nut should fit snugly without play or shake but should not bind on the thread at any point.

If the angle of the thread is correct and the thread is cut to the correct depth it will fit the nut perfectly. However, if the angle of the thread is incorrect or the lead is incorrect, the thread may appear to fit the nut but will only be touching at a few points. For this reason the thread should be checked by other methods in addition to the nut or ring gage.




Fig. 30. Trial cut to check set-up for thread cutting.




Fig. 31. Measuring screw threads.




Fig. 32. Screw thread pitch gage.




Fig. 33. Screw thread properly fitted to nut.



Fig. 34. Applying lard oil to work with small paint brush while cutting screw threads in a tool steel thread gage.

## Use Lard Oil When Cutting Screw Threads in Steel

Lard oil should be used when cutting screw threads in steel in order to produce a smooth thread. If the oil is not used a very rough finish will be caused by tearing of the steel by the cutting tool.

If lard oil is not available any good cutting oil or machine oil may be used. If trouble is experienced in producing a smooth thread, a little powdered sulphur may be added to the oil.

The oil should be applied generously preceding each cut. A small paint brush is ideal for applying the oil when cutting external screw threads, as illustrated above. Since lard oil is quite expensive, many mechanics place a small tray or cup just below the cutting tool on the cross slide of the lathe to catch the surplus oil which drips off the work. In manufacturing plants where the lathe is to be used exclusively for cutting screw threads in steel it is customary to equip the lathe with an oil pan and oil pump to provide a continuous flow of oil.

## Resetting the Tool After the Thread Has Been Started

If the thread cutting tool should need re-sharpening, or if for any other reason it is necessary to remove the thread cutting tool before the thread has been completed, the tool must be carefully re-adjusted so that it will follow the original groove when it is replaced in the lathe. There are several methods by which this can be accomplished.

Before adjusting the tool, set the point of the cutter bit square with the work, as described on page 8, and take up all the lost motion in the change gears, half nuts, etc., by pulling the belt forward by hand.

If the lathe has a compound rest, the compound rest top may be set at an angle, and by adjusting the cross feed screw and compound rest feed screw simultaneously the point of the tool can be made to enter exactly into the original groove.

If it is not convenient to use the compound rest for readjusting the threading tool, the lathe dog may be loosened, the work turned so that the threading tool will match the groove and the lathe dog tightened.

Another method that is sometimes used is to disconnect the reverse gears or the change gears, turn the headstock spindle until the point of the threading tool enters the groove in the work, and then reconnect the gears.




Fig. 35. Adjusting point of threading tool to conform with thread.

## Finishing the End of a Threaded Piece

The end of the thread may be finished by any one of several methods. The 45° chamfer on the end of the thread, as shown in Fig. 36, is commonly used for bolts, cap screws, etc. For machined parts and special screws the end is often finished by rounding with a forming tool, as shown in Fig. 37.

It is difficult to stop the threading tool abruptly so some provision is usually made for clearance at the end of the cut. In Fig. 36 a hole has been drilled in the end of the shaft, and in Fig. 37 a neck or groove has been cut around the shaft. The groove is preferable as the lathe must be run very slowly in order to obtain satisfactory results with the drilled hole.




Fig. 36. Finishing end of thread with 45° chamfer.




Fig. 37. Finishing end of thread with form tool.






Fig. 38. Thread dial indicator attached to lathe carriage.

## Use of Thread Dial Indicator in Cutting Screw Threads

A thread dial indicator or threading clock is usually used for cutting long screw threads. This device permits disengaging the half-nuts at the end of the cut, returning the carriage to the starting point by hand, and then engaging the half nuts at the correct time so that the tool will follow the original cut. This saves time on long threads and it also eliminates the necessity of reversing the lathe spindle.

The threading dial consists of a worm wheel which is attached to the lower end of a shaft and meshed with the lead screw. On the upper end of the shaft is the dial. As the lead screw revolves, the dial is turned and the numbers on the dial indicate points at which the half nuts may be engaged.

When cutting short threads it is better to leave the half-nuts engaged with the lead screw, and when the end of the cut is reached, withdraw the tool and reverse the lathe spindle to return the tool to the starting point.




Fig. 39. Face of thread dial indicator.

### Rules for Operating Thread Dial on South Bend Lathe

For all even numbered threads, close the half nuts at any line on the dial.

For all odd numbered threads, close the half nuts at any numbered line on dial.

For all threads involving one-half of a thread in each inch, such as  $11\frac{1}{2}$ , close the half nuts at any odd numbered line.

The thread dial cannot be used when cutting metric screw threads.

## Cutting Multiple Screw Threads

Multiple screw threads are used for adjusting screws and other applications where a coarse lead is desired. The depth of the thread is less than for a single thread of equal lead, making a stronger screw.

A multiple thread having two grooves is known as a double thread, one having three grooves a triple thread, etc. (See Fig. 40.) The pitch and lead of a multiple thread should not be confused. The pitch is the distance from a point on one thread to the corresponding point on the next thread, while the lead is the distance a screw thread advances in one turn.




Fig. 40. A multiple screw thread having two grooves (Double Thread)

When cutting multiple threads in the lathe the first thread is cut to the desired depth. The work is then revolved part of a turn, and the second thread cut, etc. In order to obtain an exact spacing it is advisable to mill as many equally spaced slots in the face plate for the lathe dog as there are multiple threads to be cut. For a double thread, two slots; a triple thread, three slots, etc. If it is not convenient to cut slots in the face plate, equally spaced studs may be attached to the face plate and a straight tail lathe dog used.

Another method for indexing the work when cutting multiple threads is to disengage the change gears after the first thread has been completed and turn the spindle to the required position for starting the next cut. If a double thread is being cut and there are 48 teeth in the stud gear, the spindle should be turned until 24 teeth have been passed, then the gears engaged and the second thread cut.

## Cutting Left Hand Screw Threads

A left hand screw is one that turns counter-clockwise when advancing (looking at head of screw) as shown in Fig. 42. This is just the opposite of a right hand screw. Left hand threads are used for the cross feed screws of lathes, the left hand end of axles for automobiles and wagons, one end of a turnbuckle, some pipe threads, etc.




Fig. 41. A left hand screw thread.

In cutting left hand screw threads the lathe is set up exactly the same as for cutting right hand screw threads, except that the lathe must be arranged to feed the tool from left to right, instead of from right to left, when the spindle is revolving forward.



Fig. 42. A left hand screw advances when turned counter-clockwise.

## How to Calculate Change Gears for Cutting Screw Threads

If it is necessary to cut a special thread that does not appear on the index chart of a lathe or if no index chart is available, the gears required can easily be calculated. All South Bend Lathes are even geared; that is, the stud gear revolves the same number of revolutions as the headstock spindle, and when gears of the same size are used on both the lead screw and stud, the lead screw and spindle revolve the same number of revolutions, so it is not necessary to consider the gearing between the headstock spindle and the stud gear when calculating change gears.

If simple gearing is to be used, as shown in Fig. 43, the ratio of the number of teeth in the change gears used will be the same as the ratio between the thread to be cut and the thread on the lead screw. For example, if 10 threads per inch are to be cut on a lathe having a lead screw with 6 threads per inch, the ratio of the change gears would be 6 to 10. These numbers may be multiplied by any common multiplier to obtain the number of teeth in the change gears that should be used.

**Rule**—To calculate change gears, multiply the number of threads per inch to be cut and the number of threads per inch in the lead screw by the same number.

**Example: Problem**—To cut 10 threads per inch on lathe having lead screw with 6 threads per inch.

**Solution**—  $6 \times 8 = 48$  — No. of teeth in gear on stud.

$10 \times 8 = 80$  — No. of teeth in gear on lead screw.

If these gears are not to be found in the change gear set, any other number may be used as a common multiplier, such as 3, 5, 7, etc.

When compound gearing, as shown in Fig. 44, is used, the ratio of the compound idler gears must also be taken into consideration, but otherwise the calculations are the same as for simple gearing. For example, if the compound idler gear ratio is 2 to 1, the threads cut are just twice the number per inch as when simple gearing is used.

### Diagram Showing Simple and Compound Gearing




Fig. 43. Simple gearing.




Fig. 44. Compound gearing.

## Using Taps and Dies to Cut Screw Threads in the Lathe

Taps and dies are often used for cutting screw threads in the lathe, especially in factories where maximum production is important. There are several ways in which the lathe may be set up for this kind of work, as illustrated below.

Fig. 45 shows a common hand tap being used to thread a nut which is held in the lathe chuck. The handle of the tap wrench rests against the V way of the lathe bed, and as the lathe spindle revolves slowly the tail-stock hand wheel is turned to feed the tap through the nut. Plenty of oil should be used on the tap if the nut is made of steel.

Fig. 46 shows a self-opening die mounted in the tailstock spindle of the lathe for cutting threads on studs. After starting the lathe spindle the tailstock is pushed by hand along the lathe bed until the die takes hold and starts to cut the thread, after which the die will pull the tailstock along. A die holder can be made for the tailstock to hold common button dies, but if they are used it is necessary to reverse the lathe spindle when the end of the thread has been reached.

Fig. 47 shows a die mounted on the tool rest of the lathe. When mounted in this manner the lead screw and half nuts of the lathe may be used to feed the die so a perfect lead is obtained in the thread cut.

Fig. 48 shows a lathe equipped with special fixture for holding the work on the face plate, and a turret for holding drills, boring bar and taps for boring and threading the hole.




Fig. 45. Using a tap for threading a nut in the lathe.




Fig. 46. Die mounted in tailstock of lathe for threading studs.




Fig. 47. Die mounted on lathe carriage for cutting accurate threads.





Fig. 48. Tap mounted in lathe turret for threading special nuts.



# Standard Screw Thread Forms



**AMERICAN NATIONAL SCREW THREAD**  
(Formerly U. S. Standard Screw Thread)




FORMULA


$$P = \text{Pitch} = \frac{1}{\text{No. Th'ds. Per In.}}$$

$$D = \text{Depth} = P \times .6495$$

$$F = \text{Flat} = \frac{P}{8}$$



**FRENCH AND INTERNATIONAL SYSTEM  
STANDARD SCREW THREAD**



FORMULA


$$P = \text{Pitch in MM}$$

$$D = \text{Depth of Engagement} = P \times .6495$$

$$H = \text{Depth of Thread} = P \times .6415$$

$$r = \text{Maximum Radius} = P \times .0633$$

$$F = \text{Flat} = \frac{P}{8}$$



**WHITWORTH STANDARD SCREW THREAD**




FORMULA


$$P = \text{Pitch} = \frac{1}{\text{No. Th'ds. Per In.}}$$

$$D = \text{Depth} = P \times .6403$$

$$R = \text{Radius} = .1373P$$



**SQUARE SCREW THREAD**




FORMULA


$$P = \text{Pitch} = \frac{1}{\text{No. Th'ds. Per In.}}$$

$$D = \text{Depth} = P \times .500$$

$$F = \text{Space} = P \times .500$$



**ACME SCREW THREAD**




FORMULA

$$P = \text{Pitch} = \frac{1}{\text{No. Th'ds. Per In.}}$$


$$D = \text{Depth} = \frac{1}{2} P + .010$$

$$F = \text{Flat} = .3707 P$$

$$C = \text{Flat} = .3707 P - .0052$$



**BROWN & SHARPE 29° WORM SCREW THREAD**



FORMULA

$$P = \text{Pitch} = \frac{1}{\text{No. Th'ds. Per In.}}$$

$$D = \text{Depth} = .6866 P$$

$$F = \text{Flat} = .31 P$$

$$C = \text{Flat} = .333 P$$

# Metric Screw Threads

In France and other parts of Europe the International Standard Metric Screw Threads and other systems of metric threads are used. These threads are used extensively on microscopes, telescopes and other optical and scientific instruments and surgical instruments.

Metric threads are measured in the Metric System instead of in the English system, and in order to cut them on a lathe having an English lead screw, metric transposing gears must be used. The ratio between the English System and Metric System of measurement is such that compound transposing gears having 127 teeth and 100 teeth or 127 teeth and 50 teeth may be used to cut perfect metric screw threads.

Metric transposing gears are supplied for both Standard Change Gear Lathes and Quick Change Gear Lathes having English lead screws. A metal chart similar to Fig. 51, showing the arrangement of the gears for cutting various pitches of metric screw threads, is attached to each lathe.

The form of the metric thread is similar to the American National Screw Thread form, having a 60° included angle and a flat at the top of the thread, but a small radius at the root of the thread provides greater clearance. (See Fig. 50.)




Fig. 50. International Standard Metric Screw Thread Form.

**FORMULA**  
 $P = \text{Pitch in MM}$   
 $D = \text{Depth of Engagement} = P \times .6495$   
 $H = \text{Depth of Thread} = P \times .6945$   
 $r = \text{Maximum Radius} = P \times .6623$   
 $F = \text{Flat} = \frac{P}{8}$




Fig. 49. Metric Transposing Gears Attached to Lathe.

METRIC THREAD CHART					
LEAD SCREW 8 THREADS PER INCH					
M.M. PITCH	TOOTH GEAR	TOOTH GEAR	TOOTH GEAR	TOOTH GEAR	FEED IN MM PER SINGLE REVOLUTION
6	45	FIG. 1	20	127	0.0635
6.5	45	FIG. 1	20	127	0.0635
7	45	FIG. 1	20	127	0.0635
7.5	45	FIG. 1	20	127	0.0635
8	45	FIG. 1	20	127	0.0635
8.5	45	FIG. 1	20	127	0.0635
9	45	FIG. 1	20	127	0.0635
9.5	45	FIG. 1	20	127	0.0635
10	45	FIG. 1	20	127	0.0635
10.5	45	FIG. 1	20	127	0.0635
11	45	FIG. 1	20	127	0.0635
11.5	45	FIG. 1	20	127	0.0635
12	45	FIG. 1	20	127	0.0635
12.5	45	FIG. 2	80	127	0.0635
13	45	FIG. 2	80	127	0.0635
13.5	45	FIG. 2	80	127	0.0635
14	45	FIG. 2	80	127	0.0635
14.5	45	FIG. 2	80	127	0.0635
15	45	FIG. 2	80	127	0.0635
15.5	45	FIG. 2	80	127	0.0635
16	45	FIG. 2	80	127	0.0635
16.5	45	FIG. 2	80	127	0.0635
17	45	FIG. 2	80	127	0.0635
17.5	45	FIG. 2	80	127	0.0635
18	45	FIG. 2	80	127	0.0635
18.5	45	FIG. 2	80	127	0.0635
19	45	FIG. 2	80	127	0.0635
19.5	45	FIG. 2	80	127	0.0635
20	45	FIG. 2	80	127	0.0635
20.5	45	FIG. 2	80	127	0.0635
21	45	FIG. 2	80	127	0.0635
21.5	45	FIG. 2	80	127	0.0635
22	45	FIG. 2	80	127	0.0635
22.5	45	FIG. 2	80	127	0.0635
23	45	FIG. 2	80	127	0.0635
23.5	45	FIG. 2	80	127	0.0635
24	45	FIG. 2	80	127	0.0635
24.5	45	FIG. 2	80	127	0.0635
25	45	FIG. 2	80	127	0.0635
25.5	45	FIG. 2	80	127	0.0635
26	45	FIG. 2	80	127	0.0635
26.5	45	FIG. 2	80	127	0.0635
27	45	FIG. 2	80	127	0.0635
27.5	45	FIG. 2	80	127	0.0635
28	45	FIG. 2	80	127	0.0635
28.5	45	FIG. 2	80	127	0.0635
29	45	FIG. 2	80	127	0.0635
29.5	45	FIG. 2	80	127	0.0635
30	45	FIG. 2	80	127	0.0635
30.5	45	FIG. 2	80	127	0.0635
31	45	FIG. 2	80	127	0.0635
31.5	45	FIG. 2	80	127	0.0635
32	45	FIG. 2	80	127	0.0635
32.5	45	FIG. 2	80	127	0.0635
33	45	FIG. 2	80	127	0.0635
33.5	45	FIG. 2	80	127	0.0635
34	45	FIG. 2	80	127	0.0635
34.5	45	FIG. 2	80	127	0.0635
35	45	FIG. 2	80	127	0.0635
35.5	45	FIG. 2	80	127	0.0635
36	45	FIG. 2	80	127	0.0635
36.5	45	FIG. 2	80	127	0.0635
37	45	FIG. 2	80	127	0.0635
37.5	45	FIG. 2	80	127	0.0635
38	45	FIG. 2	80	127	0.0635
38.5	45	FIG. 2	80	127	0.0635
39	45	FIG. 2	80	127	0.0635
39.5	45	FIG. 2	80	127	0.0635
40	45	FIG. 2	80	127	0.0635
40.5	45	FIG. 2	80	127	0.0635
41	45	FIG. 2	80	127	0.0635
41.5	45	FIG. 2	80	127	0.0635
42	45	FIG. 2	80	127	0.0635
42.5	45	FIG. 2	80	127	0.0635
43	45	FIG. 2	80	127	0.0635
43.5	45	FIG. 2	80	127	0.0635
44	45	FIG. 2	80	127	0.0635
44.5	45	FIG. 2	80	127	0.0635
45	45	FIG. 2	80	127	0.0635
45.5	45	FIG. 2	80	127	0.0635
46	45	FIG. 2	80	127	0.0635
46.5	45	FIG. 2	80	127	0.0635
47	45	FIG. 2	80	127	0.0635
47.5	45	FIG. 2	80	127	0.0635
48	45	FIG. 2	80	127	0.0635
48.5	45	FIG. 2	80	127	0.0635
49	45	FIG. 2	80	127	0.0635
49.5	45	FIG. 2	80	127	0.0635
50	45	FIG. 2	80	127	0.0635

Fig. 51. Metric Thread Cutting Chart for Lathe with English Thread Lead Screw and Metric Transposing Gears.


## International Standard Metric Screw Thread

DIAMETER MM.	PITCH MM.	DIAMETER MM.	PITCH MM.	DIAMETER MM.	PITCH MM.
6	1.0	18	2.5	42	4.5
7	1.0	20	2.5	45	4.5
8	1.25	22	2.5	48	5.0
9	1.25	24	3.0	52	5.0
10	1.5	27	3.0	56	5.5
11	1.5	30	3.5	60	5.5
12	1.75	33	3.5	64	6.0
14	2.0	36	4.0	68	6.0
16	2.0	39	4.0		



Fig. 52. Metric Transposing Gear Attachment for 16" Lathe.






At Left—No. 415-YA 9' x 3' New Model South Bend "Workshop" Adjustable Horizontal Motor Driven, Back-Geared Screw Cutting Precision Bench Lathe.

One of the finest small lathes we have ever built.


At Right—No. 917-C 16' x 6' New Model South Bend Pedestal Adjustable Motor Driven, Quick Change Gear, Back-Geared Screw Cutting Precision Lathe.

A popular type high quality precision lathe.



At Left—No. 8117-C 16' x 6' New Model South Bend Tool Room Underneath Belt Motor Driven, Quick Change Gear, Back-Geared Screw Cutting Precision Lathe.

A practical, efficient and popular motor driven lathe.



Works at South Bend, Indiana. This organization was founded in 1906 and has grown and developed to an enterprise occupying the buildings shown here, which have a floor space of 180,000 square feet and with a ground area of 4 1/4 acres devoted exclusively to the manufacture of South Bend Back-Geared Screw Cutting Precision Lathes.

South Bend Lathe Works  
SOUTH BEND, INDIANA, U. S. A.

