

## Lathe Drive Belt Length and Widths

Model Lathe Used on	Thickness	Width	Length	Leblond Part No.
	(in)	(in +/- 1/16")	(in)	
9" Horizontal Drive Unit	9/64	3/4"	53-1/2	PT2223N4
9" Underdrive Metal Bench	9/64	3/4	61	PT2200N3
10K Horizontal Drive Unit	9/64	3/4	50-1/4	PT2226K4
10K Underdrive Cabinet Metal Bench	9/64	3/4	61-7/8	PT2208K3
10" Underdrive Cabinet Metal Bench	5/32	1	58-1/8	PT2201R3
10" Underdrive Cabinet Leg Floor	5/32	1	61-1/2	PT2202R3
12-3/4" mounted on Steel Floor Legs	5/32	1	64-3/8	PT2229R2
12-3/4" mounted on 9" or 10" Metal Bench	5/32	1	59-1/8	PT2199R2
13" Underdrive Cabinet Leg Floor (3 step cone)	5/32	2	61-1/2	PT2195T3
13" Underdrive Cabinet Leg Floor (4 step cone)	5/32	1-1/2	61-1/2	PT2203T3
14-1/2" Underdrive Cabinet Leg Floor (3 step cone)	5/32	2-1/2	64-5/8	PT2196F3
14-1/2" Underdrive Cabinet Leg Floor (4 step cone)	5/32	1-1/2	64-1/2	PT2204F3
16" Underdrive Cabinet Leg Floor (4 step cone)	5/32	2	68-1/4	PT2205H3
16" Underdrive Cabinet Leg Floor (3 step cone)	5/32	2-1/2	68-1/4	PT2207H3
16"/24" Underdrive Cabinet Leg Floor (3 step cone)	5/32	2-1/2	77-1/2	PT2197V3
16"/24" Underdrive Cabinet Leg Floor (4 step cone)	5/32	2	76-3/8	PT2206H3