

10"-1" Collet Horizontal Motor Drive Precision Bench Lathe

Series "S"—Quick Change Gear—Back-Geared—Belt Drive to Spindle

The 10-inch Swing I" Collet Capacity Quick Change Gear Bench Lathe with horizontal motor drive is very attractively priced. The quick change gear box provides a wide range of right and left hand screw threads and power carriage feeds. See page 48 for specifications of this lathe.


A Special Headstock, with $1\frac{3}{8}$ " hole through the spindle and 1" capacity through collet, makes this lathe especially practical for tool room and production operations on parts made of bar stock or tubing. Spindle speeds, 50 to 1357 R.P.M. are provided by two-speed motor drive pulleys.

Improved Features of lathe include: alloy steel headstock spindle, carburized, hardened, ground, and superfinished; integral headstock bearings; ball thrust bearing; double wall apron with all gears of steel, and multiple disc friction clutch; micrometer graduated collars; quick change gear box for threads and feeds; and semi-steel lathe bed.

Regular Equipment included in price of lathe consists of:

34 H.P. instant reversing motor; reversing switch; wiring; V-belt; leather belt; large and small face plates; tool post; thread cutting stop; centers for headstock and tailstock spindles; spindle sleeve; wrenches; quick change gear box; installation plan; and book "How to Run a Lathe." Bench is not included. Blue print for making bench supplied on request, see pg. 99.

10" LATHER



End View of Lathe Showing Adjustable Horizontal Motor Drive

10-inch l" Collet Horizontal Motor Driven Bench Lathes Quick Change Gear—less Bench

Bed Lengths	3-ft.	3½-ft.	4-ft.	41/2-ft.
Distance Between Centers	15 ¾-in.	20 ¾-in.	26 ¾-in.	33 ¾-in.
Catalog Number	487-Y	487-Z	487-A	487-R
Shipping Weight, Crated	521 lbs.	546 lbs.	571 lbs.	596 lbs.
Code Word.	Dunac	Duneg	Duzem	Duzow

56





